



**SAFETY SYSTEM®**  
YOUR PROTECTOR

**Sir Safety System S.p.A. Single-member company**  
Wholly-owned subsidiary of Sir Holding Srl  
Via dei Fornaciai, 9 - Santa Maria degli Angeli  
06081 Assisi - Perugia - Italy  
Tel.+39 075.8043737 - Fax +39 075.8048686

VAT Nr. IT 03359340548  
Viale Europa 74  
20090 Cusago Milano  
Tel. +39 02.90394575  
Fax +39 02.90394441

**TECHNICAL SHEET**

**export@sirsafety.com**  
**www.sirsafety.com**

Quality Management  
System Certificate  
UNI EN ISO 9001:2015

<b>Name: STARMAX JACKET</b>	<b>Code: MC3914HD</b>	<b>MC39 HIGH VISIBILITY CLOTHING - WINTER KNITWEAR</b>
-----------------------------	-----------------------	--

**Description**

High Visibility Softshell Jacket, inner layer in 144 filaments micro-fleece. Central zipper closure, bottom part of the jacket adjustable with drawstring and detachable hood with zipper and drawstring; detachable sleeves with zipper, cuffs adjustable with Velcro, two muff pockets with zipper closure and chest pocket with zipper.

Three different overlapping layers in Softshell fabric create a unique combination that guarantees high levels of comfort: the polyester micro-fleece inner layer makes the fabric soft and warm, the TPU membrane coupled with the polyester outer fabric allows moisture transpiration and thermoregulation, always keeping the body dry, and making the garment windproof and storm-proof.

The product has been designed and manufactured to comply with Regulation (EU) 2016/425 and subsequent amendments.

EN ISO 20471


Class 2:

- 0.50 m fluorescent material;
- 0.13 m reflective material.

V@Á aá Áccí} aÁca} B Á ÜSUE ÖYÍ Á Ácaá



<b>Category</b> <b>II</b>	<b>Colours</b> <b>HI-VIS ORANGE/BLUE</b>	<b>Available Sizes</b> <b>S - 4X</b>
------------------------------	---	---

<b>Quantity/Carton</b>          <b>10</b>	<b>EC Standards</b> <b>EN ISO 20471</b>  <b>Class:2</b>	<b>Important Information</b> General and Road Construction, Road sign work, Road and plants maintenance, Transport, Logistics, Service and assistance companies, Emergency response companies.  Keep in a cool dry place, far from heat sources and direct light. Make sure the garment is in good condition, undamaged and clean before use. Once you become aware of a damage, you should immediately replace it.  We recommend to follow the washing instructions.
<b>Dexterity</b>		<b>Storage and cleaning</b> Data retrieval failed for the subreport,